Date:

Thursday, 01/05/2008 12:48:25 PM

Ušer:

Julie Lecocq

## **Process Sheet**

Customer

: CU-DAR001 Dart Helicopters Services

Job Number **Estimate Number**  : 38951

P.O. Number

: 10346

This Issue Prsht Rev.

**Previous Run** 

: 01/05/2008

: NC

: //

: 38660

: SKIDTUBES Type

**Part Number** S.O. No. :

**Drawing Number** 

**Drawing Name** 

: D2596 · D2596 REV D

**Project Number** 

: N/A

**Drawing Revision** Material **Due Date** 

: 10/05/2008

: 205 SKIDTUBE "I" BEAM

Qty:

4 Um:

Each

Written By

Comment

First Issue

Checked & Approved By

: Est: D 99.02.02

Changed QA to QC, Added Step 6 and Cost D

Est Rev:E 07-07-09 Incorperated DEO 9183 JLM

**Additional Product** 

Job Number:



Seq. #:

**Machine Or Operation:** 

Description:

1.0

D25003100

Ext'n -`I' Beam Web 4"



Comment: Qty.:

1.0000 Each(s)/Unit Total:

4.0000 Each(s)

Extrusion "I" Beam Web 4"

Pick:

Qty

Part Number D2500-3-100

Description Extrusion

Batch

2.0

SKIDTUBES 1

SKIDTUBESS RESOURCE





Comment: LANDING GEAR RESOURCE 1

- 1- Cut D2500-3-100 to length: 99.5"
- 2- Use Jig DT8093 to drill pilot holes #30
- 3- Open to 0.630" diameter as per Dwg D2596
- 4- Deburr

3.0 HAND FINISHING HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

Acid Etch and Alodine per QSI 005 4.1



INSPECT WORK TO CURRENT STEP

4.0

QC5



Comment: INSPECT WORK TO CURRENT STEP



## **Dart Aerospace Ltd**

W/O:		WORK ORDER CHA	NGES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
-							
	:						
Part No	•	PAR #: Fault Category:	NCR: Yes	No DQ	<b>\</b> :	Date: _	

QA: N/C Closed: \_\_\_\_ Date: \_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)								
DATE		Description of NC	Corrective Action Section B			Verification	A	A		
	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector		
					7					
				*)						

NOTE: Date & initial all entries

Date:

Thursday, 01/05/2008 12:48:25 PM

Customer: CU-DAR001 Dart Helicopters Services

User:

Julie Lecocq

**Process Sheet** 

Drawing Name: 205 SKIDTUBE "I" BEAM

Job Number: 38951

Part Number: D2596

Job Number:



Seq. #:

**Machine Or Operation:** 

**Description:** 

5.0

PACKAGING 1

PACKAGING RESOURCE #1

Comment: PACKAGING RESOURCE #1

Identify and Stock

Location: 46



6.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



## **Dart Aerospace Ltd**

W/O:		WORK ORDER CH	WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
		•						
2								

Part No:	PAR #:	Fault Category:	NCR: Yes	No DQA:	Date:
			QA: N/	Date:	

NCR:		WORK ORDER NON-CONFORMANCE (NCR)								
DATE		Description of NC	Corrective Action Section B			Verification	Ammunuml	A		
	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector		
					·					
							Ø.			
				$\mathcal{L}$						
				is the second se						

NOTE: Date & initial all entries

